

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representative	es Present During the Inspection:	
OGM	Pete Hess Environmental Scientist III	
Company	Guy Davis Environmental Scientist	

Inspection Report

Permit Number:	C0150019			
Inspection Type:	COMPLETE			
Inspection Date:	Tuesday, December 20, 2005			
Start Date/Time:	12/20/2005 8:20:00 AM			
End Date/Time:	12/20/2005 10:40:00 AM			
Last Inspection:	Tuesday, September 20, 2005			

Inspector: Pete Hess, Environmental Scientist III

Weather: Overcast, 30's F. InspectionID Report Number: 822

12/21/2005

Accepted by: whedberg

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO Site: COTTONWOOD/ WILBERG

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	6,886.88	
Total Disturbed	62.82	
Phase I		
Phase II		
Phase III		

Mineral Ownership Types of Operations

✓ Federal ✓ Underground State Surface County Loadout ✓ Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Cottonwood / Wilberg Mine remains in temporary cessation status.

The Permittee continues to meet the Special Permit Condition included as Attachment "A" of the current State permit, which requires that the Permittee submit all surface and ground water monitoring information in an electronic form to the Division EDI on a quarterly basis.

Both the main facilities area and the Cottonwood Fan portal area are under approximately 2 to 3 inches of snow.

The road inby the main facilities gate had not been plowed.

Inspector's Signature

Date

Tuesday, December 20, 2005

Pete Hess, Environmental Scientist III Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150019 Inspection Type: COMPLETE

Inspection Date: Tuesday, December 20, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	~		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	~			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.8	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓			
22.	Other				

Permit Number: C0150019
Inspection Type: COMPLETE

Inspection Date: Tuesday, December 20, 2005 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Permittee anticipates submitting a Phase 1 bond release application to the Division for the Deer Creek 9th East portals (located above the Wilberg Mine fan) in January, 2006. The Permittee also intends to apply for a Phase 2 / Phase 3 bond release for the reclaimed Cottonwood refuse disposal area during 2006.

4.a Hydrologic Balance: Diversions

All diversions are covered with snow. Mr. Davis indicated that the ditch which exists on the cut bank side of the elevated road adjacent to the bin wall (main facilities area) has had rock rubble removed since the September inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee's qualified representatives (Messrs. John Christensen and Rick Cullum) performed the third quarter of 2005 sediment pond inspections for the North and South ponds, as well as the waste rock site pond on September 20, 2005. The inspection report was completed on September 29, 2005, followed by Mr. Christensen's P.E. certification on October 14, 2005. There were no unstable conditions or other hazards reported for any of the ponds. The North and South ponds have 0.38 and 0.32 acre feet of sediment storage capacity remaining prior to reaching the 60% sediment cleanout elevation. The waste rock pond has 2.23 acre feet of sediment storage capacity remaining, prior to cleanout.

4.d Hydrologic Balance: Water Monitoring

The Permittee submitted the November UPDES discharge monitoring reports for the Cottonwood/Wilberg Mine (outfalls 001A and 004A) on December 19, 2005. Outfall 001A reported a flow of 0.02 mgpd from the Cottonwood Creek discharge point. There were no exceedances of effluent parameters. UPDES 004A was reported as "no discharge".

7. Coal Mine Waste, Refuse Piles, Impoundments

The Cottonwood / Wilberg waste rock sites (the active and the reclaimed areas) were inspected by Mr. John Christensen, P. E., on September 20, 2005, with the required P.E. certification being performed on October 14, 2005. There were no indications of hazardous or unstable conditions reported. No coal waste is being hauled to the waste rock site; only sediment pond cleanout is being disposed of here. The certified inspection reports were forwarded to the DOGM on October 17, 2005.

16.a Roads: Construction, Maintenance, Surfacing

The Permittee has made a temporary repair to the bin wall area which is located within the main facilities area. Fill has been placed in the void, and a berm has been placed on the road surface above the failure area to direct runoff down the road, such that it can not wet the back filled void. When the Mine is re-opened, the Permittee and the Division will need to re-evaluate this repair to determine if it is adequate for the amount and weight of the vehicles which will be passing over it.